

Timber Disclaimer: All timbers lose a degree of tanning, some more than others. Timber in an external environment is susceptible to cracking, shelling and moving due to the natural drying process, this does not take away from the durability of the product. In time timber may develop surface discolouration , this is caused by natural mould feeding on the tannins and should disperse as the timber dries and turns silver. Logic are not liable for this natural process and can not be held responsible for any of these natural processes. All products to be installed in conjuntion with the supplied installation guide, following the steps & guidance. VELOX Rapid Edge 100003507705 / Patent no:GB2600394 / Registered Design - Europe:008214910 & UK:90082149100001